

Korenix JetNet Industrial Managed Switch 4518 SOFTWARE RELEASE Notes

Before Upgrade

Before you use the Switch firmware, please ensure that you know the product number and use the correct firmware version. By reading the file, you can know the new feature and changes, the fixed bugs and the restrictions. You can find the latest firmware in the Korenix web site, <http://www.korenix.com> or get the help from Korenix Customer Support, Korecare@korenix.com.

About This Software Version

The version number and the release date.

Version	Release Date	Model
V1.3 (Armboot v1.0.0.3)	Nov. 03, 2011	JetNet 4518
V1.1 (Armboot v1.0.0.3)	Nov. 4, 2009	JetNet 4518

CAUTION: You can only update the correct firmware to the JetNet switches. Ensure the product model number before you start updating.

New Changes and Improvement:

The following changes apply to the version v 1.3:

- Web UI supports Chinese simplified language (中文簡體字版Web UI)
- Add Modbus TCP slave
- Apply the new time setting format for daylight saving time
- SFP
 - Add SFP eject/scan function
 - Add SFP enable/disable DDM function
 - Add new SFP warning event

Known Restrictions or Limitation

- The 2 SFP just support 100Base-FX SFP Transceiver.