

Shortage & Replacement Notice

Dear all partners,

Korenix appreciates your great support on industrial networking business.

Due to Acute AQ8828 chipset EOL issue caused by foundry production line close, the shipment of the models listed below will be delayed and we will take urgent action to revise new models for replacement. We appreciate your understanding and we will keep focus on providing more enhanced and value-added products for you.

➤ Shipment Delayed Model Series:

JetNet 5018G (v2.0)	Industrial 16+2G Gigabit Managed Ethernet Switch
JetNet 5012G	Industrial 8+4G Gigabit Managed Ethernet Switch
JetNet 4518	Industrial 18-Port Managed Ethernet Switch
JetNet 3018G (v2.0)	Industrial 16+2G Gigabit Ethernet Switch
JetNet 5428G	Industrial Rackmount 24+4G Managed Ethernet Switch
JetNet 5010G-p	Industrial 8+2 GbE TX/SFP Combo, Managed Switch board

➤ Replacement Plan:

Original Model	Replace Model	Schedule
JetNet 5018G (v2.0)	JetNet 5020G	2015 Q3-Q4
JetNet 5012G		
JetNet 4518		
JetNet 3018G (v2.0)	JetNet 3018G (v3.0)	2015 Q3-Q4
JetNet 5428G	JetNet 5428G (v2.0)	2015 Q3-Q4

Person responsible for making this declaration



Richard Fan
Product VP



Mike Liu
R & D VP